

Exhibit 4 - Photographs



Vineyard #1 – proposed critical dip location



Vineyard # 1 – culvert replacement at Site 2

Exhibit 4 - Photographs



Vineyard # 2 – critical area planting



Vineyard # 2 – grade stabilization

Exhibit 4 - Photographs



Vineyard # 2 – grassed waterway



Vineyard #3 – rill on Site 2 right road

Exhibit 4 - Photographs




Vineyard #3 – rills on Site 29 right road



Vineyard #3 – site 6 outlet needing rock



Vineyard #3 - Site 16 wash out



Vineyard #3 – Site 28 armored fill location

Exhibit 4 - Photographs



Vineyard #3 – Site 30 ford enhancement



Vineyard #3 - Site 31 right road berm removal

Exhibit 4 - Photographs



Vineyard #3 – upper vineyard dirt road



Vineyard #4 – grassed waterway

Exhibit 4 - Photographs



Vineyard #4 – road erosion site